

Adelaide Briton Cement

Project: Cement Factory Silo

Category: Corrosion Protection & Stabilisation

Completion

Date: January 2011

Product: Rhino 100% Pure Polyurea

Dealer: Adelaide Waterproofing Services

Job Description:

These disused silos were causing a safety issue for workers as the top concrete band was starting to crumble and pieces were breaking off causing an unsafe access area below.

The Rhino Linings Approved Applicator, Adelaide Waterproofing Services, was able to address the problem using Rhino Linings Spray on 100% Pure Polyurea. This process included pressure cleaning, chipping off all loose cement and sealing with Rhino Linings 100% Pure Polyurea. An aesthetically pleasing finish was not required, however Rhino 100% Pure Polyurea encapsulated the concrete permanently locking it behind an impermeable barrier.

Rhino is the perfect solution for situations such as this, due to its capability to be sprayed on to just about any substrate, regardless of the surface finish, to any required thickness.

